Title of the Master's Degree: Physics of Materials

Semester: 2

Title of the Course Unit (UE): Fundamental

Title of the Subject: Microstructural Control of Steels

Credits: 4

Coefficients: 2

Content of the Subject:

I- Structure of Steels

- 1. Fe-C Equilibrium Diagram
- 2. Non-alloy Steels
- 3. Alloy Steels
- 4. Effect of Controlled Precipitation
- 5. Effect of Fundamental Ferrite Size

II. Microstructural Transformations of Steels

- 6. Isothermal Transformation of Steels
- 7. Transformation of Austenite to Pearlite: Mechanism and Morphology, Effect of Temperature and Grain Size, Strength of Pearlite.
- 8. Transformation of Austenite to Martensite: Characteristics of Martensite Transformation, Martensite Morphology, Mechanism and Kinetics of Transformation, Strength and Hardness of Martensite.
- 9. Transformation of Austenite to Bainite
- 10. Isothermal Transformation of Non-eutectoid Steels
- 11. Continuous Transformation in Ordinary Carbon Steels.
- 12. Effect of Grain Size on Mechanical Properties
- 13. Effect of Austenite Grain Size on Ferrite Morphology.
- 14. Transformation of Pearlite to Ferrites and Cementites: Eutectoid Transformation, Perlite Structure, Kinetics of Perlite Transformation, Interphase Precipitation.

III. Transformation of Martensite and Bainite:

- 15. General Considerations
- 16. Kinetics of Martensitic Transformation
- 17. Crystallography of Martensitic Transformation
- 18. Morphology of Martensites

المحتوي:

بنية الفولاذ

- 1. مخطط اتزان الاطوار لFe-C
 - 2. الفولاذ غير المسبوك
 - 3. الفولاذ المسبوك
 - 4. تأثير الترسيب المتحكم به
- 5. تأثير البعد الحبيبي للفريت الأولي

التحولات المجهرية للفولاذ

- 1. التحول الإيزوثيرمي للفولاذ
- 2. التحول من الأوستينيت إلى البيرليت: آلية التحول و شكل الحبيبات، تأثير درجة الحرارة و حجم الحبيبات، صلادة و متانة البيرليت.
 - 3. التحول من الأوستينيت إلى المارتنزيت: خصائص التحول، شكل المارتنزيت، آلية و ميكانيزم التحول، قوة و صلابة المارتنزيت.
 - 4. التحول من الأوستينيت إلى البينيت
 - 5. التحول الإيزوثيرمي للفولاذ غير الإيوتكتويدي
 - 6. التحول المستمر في الفولاذ الكربوني العادي
 - 7. تأثير حجم الحبيبات على الخواص الميكانيكية
 - 8. تأثير حجم حبيبات الأوستينيت على شكل الفربت
- 9. التحول من البيرليت إلى الفريت والسمنتايت: التحول الإيوتكتويدي، بنية البيرليت، الية التحول، الترسيب

التحول من المارتنزيت و البينيت:

معلومات عامة

الية التحول المارتنزيتي

التبلور في التحول المارتنزيتي

الشكل المورفلوجي لحبيبات المارتنسيتات